

Material Safety Data Sheet Part #30333 & 30334

1. CHEMICAL PRODUCT AND COMPANY IDENTIFICATION

Product Name: Fluid Weld

Company Address:

Seal-Lock International

19224 Allen Rd.

Trenton, MI 48183

Region: United States

Contact Information:

Telephone: 800-521-2936

Emergency Telephone: 800-521-2936

www.seallock.com

2. COMPOSITION/INFORMATION ON INGREDIENTS

This product has been determined to be nonhazardous, in accordance with 29 CFR 1910, Subpart Z, Toxic and Hazardous Substances, Occupational Safety and Health Administration (OSHA) and Threshold Limit Values for Chemical Substances and Physical Agents in the Work Environment, American Conference of Governmental Industrial Hygienists (ACGIH)

3. PHYSICAL/CHEMICAL CHARACTERISTICS

Boiling Point: 180°F

Specific Gravity: N/A

Vapor Pressure: N/A

Melting Point: N/A

Vapor Density (air=1): N/A

Evaporation Rate: As water

Solubility in Water: Complete

Appearance and Odor: White/mild

4. FIRE FIGHTING MEASURES

Flash Point: None - Self Extinguishing

Special Fire Fighting Procedures: N/A

Extinguishing Media: Nonflammable

Unusual Fire or Explosion Hazards: None.

Flammable Limits: N/A

LEL/UEL: N/A

5. REACTIVITY DATA

Stability: Stable

Hazardous Polymerization: Will not occur.

Conditions To Avoid: N/A

Incompatibility: None

Hazardous Decomposition Products: None

6. HEALTH HAZARD DATA

Routes of Entry/Signs and Symptoms of Exposure: Inhalation: Yes Skin: Yes Ingestion: N/A

Health Hazards (Acute & Chronic): None special. Do not ingest. Avoid eye contact. Follow common safety practices.

Carcinogens: None listed under OSHA, IARC, or NTP **Signs/Symptoms of Exposure:** None special, except eye irritation.

Medical Conditions Aggravated by Exposure: None known.

Emergency and First Aid Procedures: Eyes: Flush immediately with plenty of water for 15 minutes, holding lids apart to ensure flushing of entire surface. Object is to wash eyes within several seconds after contact to flush material out, then seek medical attention immediately. Skin: Wash affected area with water.

7. PRECAUTIONS FOR SAFE HANDLING AND USE

Steps To Be Taken In Case Material Is Released Or Spilled: Flush with water to sewer.

Waste Disposal Method: Dilute 1 part to 100 parts water and flush through sewer.

Precautions To Be Taken In Handling And Storing: Do not ingest, avoid eye contact. **Other Precautions:** None.

8. CONTROL MEASURES

Respiratory Protection: None required, not volatile.

Protective Gloves: No

Eye Protection: Normal, for chemical use.

Ventilation: Local Exhaust: N/A - Special: N/A - Mechanical (General): N/A - Other: N/A

Other Protective Clothing Or Equipment: None. **Work/Hygienic Practices:** None special.